

NCC HARMONY
CONSTRUCTION PROGRESS IMAGES (Nov 07 to Jan 09)



Site before excavation (Nov-07)



Site after fencing and shoring (Feb-08)



General excavation in progress (Apr-08)



Excavation, Transportation in progress (Jul-08)



Boring of piles in progress (Aug-08)



Concreting of piles in progress (Sep-08)

NCC HARMONY
CONSTRUCTION PROGRESS IMAGES (Nov 07 to Jan 09)



Pile cap excavation in progress (Oct-08)



Pile head breaking in progress (Oct-08)



Blinding for pile cap in progress (Nov-08)



Block work for pile cap in progress (Nov-08)



Raft work in progress Tower A (Nov-08)



Blinding of raft in progress (Nov-08)

NCC HARMONY
CONSTRUCTION PROGRESS IMAGES (Nov 07 to Jan 09)



Waterproofing works in progress (Dec-08)



Reinforcement works in progress (Dec-08)



Retaining wall steel work in progress (Dec-08)



Raft works in progress Tower B (Dec-08)



Steelwork for lift wall in progress (Jan-09)



Concreting for lift wall in progress (Jan-09)